



Frequency Block Change Price List

9 January 2009

**Contact the Lectrosonics Service Department for more information.
Please have your equipment nearby when you call so you will be able
to answer questions such as model number, serial number, firmware revision, etc.**

Prices in US Dollars

Model	Current Product Block Change	
SM/SMA	\$270	
SMD/SMDA	270	
SMQ/SMQA	285	
MM400/A	285	N/A for BL470, 19, 20 - must replace
MM400B/C	285	
UM400	275	N/A for BL470, 19, 20 - must replace
UM400A	275	
UM450	310	
UH400	375	
UH400A	375	
UT	295	
IFBT4	465	
UCR401	345	
UCR411A	565	
VRM	465	Upgrade to wideband
VRFIELD	465	Upgrade to wideband

Model	Current Product Exchange Only	
LMA	\$495	Replace w/ LMA
IFBR1A	361	Replace w/ IFBR1A
VRS	225	Replace w/ VRS
VRT	389	Replace w/ VRT
R400A	467	Replace w/ R400A
UCR100	357	Replace w/ UCR100

Model	Discontinued Products Exchange Only (for products manufactured after 18 February 2004)	
UCR201	\$965	Replace w/ UCR401
UCR211	1,305	Replace w/ UCR411A
UCR411	1,305	Replace w/ UCR411A
UM200B/C	780	Replace w/ UM400A
UM250B/C	995	Replace w/ UM450
UM400	780	Replace w/ UM400A
MM200	715	Replace w/ MM400C
MM400/A	715	Replace w/ MM400C
UM100	495	Replace w/ LMA
IFBT1	615	Replace w/ IFBT4

For reference: Current Model List Price November 2008	
SMA	\$1,525
SMDA	1,625
SMQA	1,795
MM400C	1,325
MM400C	1,325
UM400A	1,440
UM400A	1,440
UM450	1,835
UH400A	1,135
UH400A	1,135
UT	1,325
IFBT4	1,140
UCR401	1,785
UCR411A	2,415
VRMWB	1,920
VRFIELDWB	2,995
LMA	\$915
IFBR1A	668
VRS	415
VRT	720
R400A	865
UCR100	660
UCR401	\$1,785
UCR411A	2,415
UCR411A	2,415
UM400A	1,440
UM450	1,835
UM400A	1,440
MM400C	1,325
MM400C	1,325
LMA	915
IFBT4	1,140