

### Block or Band Change

Includes labor and circuit board required to change the block/band  
Any additional parts necessary for repair are charged in addition  
Not all blocks/bands available. Discontinued products have limited boards/parts available

For an exact quote, contact [service.repair@lectrosonics.com](mailto:service.repair@lectrosonics.com)

Prices effective May 1, 2017

<u>List Price</u>	<u>Block Change</u> (printed circuit board assemblies included in pricing)
395.00	HH or HHA
375.00	HM or HMA
325.00	IFBR1A (UHF ONLY)
550.00	IFBT4 (UHF ONLY)
525.00	LMB
550.00	LR
425.00	LT
550.00	Octopack
550.00	R400A
375.00	SMA / SMDA / SMQA / SMV / SMQV
575.00	SSM
590.00	SR/SRA/SRB
800.00	SRC
350.00	UCR100
395.00	UCR401
800.00	UCR411A
475.00	UH400A and UH400TM
600.00	UM400A
395.00	UT
795.00	VRM and VRFIELD - WB/WBL only
295.00	VRS/E01
350.00	VRT
400.00	VRT2
425.00	WM
238.50	Distribution Amplifier Block Change or Wide Band Upgrade [UMC200D, UMC16, UDM6(S)(pair), UDM5(S)(pair), UFM50, UFM230] Parts not included in price.

