

Block or Band Change

Price includes labor and circuit board required to change the block/band.
 Not all blocks/bands available. Discontinued products have limited boards/parts available.
 For a quote or questions, contact service.repair@lectrosonics.com or call 1-800-821-1121.
 Prices effective June 1, 2020

<u>Price</u>	<u>Block Change (printed circuit board assemblies included in pricing)</u>
420.00	HHA
390.00	HMA
620.00	IFBT4 (UHF ONLY)
625.00	LMB
565.00	LR
440.00	LT
565.00	Octopack
650.00	R400A
475.00	SMWB / SMDWB
450.00	SMV / SMQV
700.00	SSM
675.00	SR/SRA/SRB
825.00	SRC
350.00	UCR100
410.00	UCR401
850.00	UCR411A
1200.00	VRM2
325.00	VRS/E01 (Limited Availability)
420.00	VRT2
450.00	WM
245.00	Distribution Amplifier Block Change or Wide Band Upgrade [UMC200D, UMC16, UDM6(S)(pair), UDM5(S)(pair), UFM50, UFM230] Parts not included in price.

Products are eligible for block change only within 7 years from the date of manufacture/original sale with the exception distribution amplifiers.

Housings may be marred when removing serial number plates or during the engraving process. Units with block information engraved on the housing will have a strikethrough line across the old frequency information and the new frequency data engraved next to it. Customers may have housings replaced at their request at an additional cost (contact the Repair Department for housing pricing).

All products will be updated with the latest firmware and specifications to be in compliance with current FCC regulations.

Any additional parts necessary to repair the item to proper working order will be added to the price shown.