

### Block or Band Change

Includes labor and circuit board required to change the block/band

Any additional parts are charged in addition

Not all blocks/bands available. Discontinued products have limited boards/parts available

For an exact quote, contact [service.repair@lectrosonics.com](mailto:service.repair@lectrosonics.com)

Prices effective May 1, 2017

<u>List Price</u>	<u>Block Change (printed circuit board assemblies included in pricing)</u>
395.00	HH or HHA
375.00	HM or HMA
325.00	IFBR1A (UHF ONLY)
550.00	IFBT4
550.00	LMA
525.00	LMB
550.00	LR
425.00	LT
320.00	MM400C
550.00	Octopack
550.00	R400A
375.00	SMA / SMDA / SMQA / SMV / SMQV
575.00	SSM
590.00	SR/SRA/SRB
800.00	SRC
350.00	UCR100
395.00	UCR401
800.00	UCR411A
475.00	UH400A and UH400TM
600.00	UM400A (UM400 no longer available)
350.00	UM450
395.00	UT
795.00	VRM and VRFIELD - upgrade to WB/WBL only
295.00	VRS/E01
350.00	VRT
400.00	VRT2
425.00	WM
238.50	Distribution Amplifier Block Change or Wide Band Upgrade [UMC200D, UMC16, UDM6(S)(pair), UDM5(S)(pair), UFM50, UFM230] Parts not included in price.