

Block or Band Change

Includes labor and circuit board required to change the block/band

Any additional parts are charged in addition

Not all blocks/bands available. Discontinued products have limited boards/parts available

For an exact quote, contact service.repair@lectrosonics.com

Prices effective May 1, 2017

List Price	Block Change (printed circuit board assemblies included in pricing)
395.00	HH or HHA
375.00	HM or HMA
325.00	IFBR1A (UHF ONLY)
550.00	IFBT4
550.00	LMA
525.00	LMB
550.00	LR
425.00	LT
320.00	MM400C
550.00	Octopack
550.00	R400A
375.00	SMA / SMDA / SMQA / SMV / SMQV
575.00	SSM
590.00	SR/SRA/SRB
800.00	SRC
350.00	UCR100
395.00	UCR401
800.00	UCR411A
475.00	UH400A and UH400TM
600.00	UM400A (UM400 no longer available)
395.00	UT
795.00	VRM and VRFIELD - upgrade to WB/WBL only
295.00	VRS/E01
350.00	VRT
400.00	VRT2
425.00	WM
238.50	Distribution Amplifier Block Change or Wide Band Upgrade [UMC200D, UMC16, UDM6(S)(pair), UDM5(S)(pair), UFM50, UFM230] Parts not included in price.