

Block or Band Change

Price includes labor and circuit board required to change the block/band.
 Not all blocks/bands available. Discontinued products have limited boards/parts available.
 For a quote or questions, contact service.repair@lectrosonics.com or call 1-800-821-1121.

Prices effective April 15, 2018

Price	Block Change (printed circuit board assemblies included in pricing)
395.00	HHA
375.00	HMA
325.00	IFBR1A (UHF ONLY)
600.00	IFBT4 (UHF ONLY)
625.00	LMB
550.00	LR
425.00	LT
550.00	Octopack
625.00	R400A
425.00	SMV / SMQV
575.00	SSM
620.00	SR/SRA/SRB
800.00	SRC
350.00	UCR100
395.00	UCR401
825.00	UCR411A
875.00	VRM and VRFIELD - WB/WBL only
310.00	VRS/E01 (Limited Availability)
375.00	VRT (Limited Availability)
400.00	VRT2
425.00	WM
238.50	Distribution Amplifier Block Change or Wide Band Upgrade [UMC200D, UMC16, UDM6(S)(pair), UDM5(S)(pair), UFM50, UFM230] Parts not included in price.

Products are eligible for block change only within 7 years from the date of manufacture/original sale with the exception distribution amplifiers.

Housings may be marred when removing serial number plates or during the engraving process. Units with block information engraved on the housing will have a strikethrough line across the old frequency information and the new frequency data engraved next to it. Customers may have housings replaced at their request at an additional cost (contact the Repair Department for housing pricing).

Any additional parts necessary to repair the item to proper working order will be added to the price shown.